


Quick Screen

Tool Overview

- Very simple, qualitative tool to identify and document ergonomic risk factors present at your worksite



Quick Screen Data Collection

- Lift outside power zone (or very heavy lift)



- Looking up, down, or to the side



- Heavy pushing



- Working away from the body



- Heavy pulling



- Bad grip



- Heavy carrying



- Hand-arm Vibration



- Contact stress



When To Use It

- Ergo walks
- Prioritizing jobs for analysis
- Tool for supervisors and industrial athletes to escalate issues to assessment team

Quick Screen Data Collection

- Lift outside power zone (or very heavy lift)



- Looking up, down, or to the side



- Heavy pushing



- Working away from the body



- Heavy pulling



- Bad grip



- Heavy carrying



- Hand-arm Vibration



- Contact stress



Lift outside power zone (or very heavy lift)



Heavy pushing



Heavy pulling



Heavy carrying



Looking up, down, or to the side



Working away from the body



Hand-arm Vibration



Contact stress




Bad grip



Outputs

- Flags the job for further analysis



The screenshot displays a software interface for ergonomics assessment. On the left is a vertical sidebar with icons for a plus sign, a grid, a calendar, a person, a graduation cap, and a bar chart. The main content area has a teal header with a hamburger menu icon and the text 'Ergonomics'. Below the header, the breadcrumb path 'Acme Corp: New York, NY > Assembly Line > Assembly Line Utility' is shown. The main section is titled 'Quick Screen' with an information icon. A red flag icon is next to the text 'Heavy lifting or lifting outside power zone'. Below this, there are edit and delete icons. At the bottom, a red text message states: 'This job has been flagged for additional assessment using the Job Screen.'

